SELFRIDGE FIELD, BUILDING NO. 197
(Motor Repair Shop)
(BE Maintenance Shop)
E. of Jefferson Ave. between George and Railroad Sts.
Mt. Clemens vicinity
Macomb County
Michigan

HAER No. MI-116-G

HAER MICH 50-MICLELY, 16-

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN ENGINEERING REGORD
National Park Service
Great Lakes Systems Office
Department of the Interior
1709 Jackson Street
Omaha, NE 68102-2571

HAER MICH 50-MTCLEN, IG-

HISTORIC AMERICAN ENGINEERING RECORD

SELFRIDGE FIELD,
BUILDING #197 (MOTOR REPAIR SHOP) HAER No. MI-116-G
(BE Maintenance Shop)

Location:

East of Jefferson Avenue between George and Railroad Streets Selfridge Air National Guard Base, Mt. Clemens vicinity, Macomb County, Michigan

U.S.G.S. Mount Clemens East Quadrangle, Universal Transverse Mercator Coordinates: 17.350440.4718980

Significance:

This renovated building represents the functional structures erected during the initial period of permanent facility construction at Selfridge.

Description:

This building is a single story, rectangular plan, 88-foot wide by 32 foot deep, flat-roofed concrete block building that rests on a concrete slab foundation and is shielded by a built up pitch and gravel roof with a metal fascia. A 12 by 20 foot dependency occurs at the southwest corner of the main building. It is reduced in height and is distinguished by an engaged square brick standard bond smoke stack. The character of its principal (north) elevation is defined by five original vehicular entrance bays, four of which are now sealed by concrete block curtain walls. An original pedestrian entry door now shielded by a pent roof metal roof stoop occurs at northeast corner of the building and a second entry and flanking steel window occur in the former vehicular entry bay at the building's northwest corner. The side elevations of the vehicular bays were originally identical, consisting of two large window voids with concrete sills. Each has now been enclosed with concrete block and glass block and a louvered vent now pierces the east elevation. The smokestack dependency reveals small glass block windows in its west and south elevations.

The interior of the building originally consisted almost entirely of vehicular service bays, including a grease pit in the westernmost bay, while an 8 foot-wide rank of rooms was partitioned off by frame walls at the eastern end of the building to house an office and stock room. Today the building is entirely open space.

History:

This "Motor Repair Shop" was erected in 1933 from plans provided by the War Department during Selfridge's initial enlargement. The current boiler room was added in 1943 from plans by the U.S. Engineers Field Office at Selfridge. Some minor alteration and upgrades occurred in 1946 and 1955. In 1974 the

Selfridge Field, Building #197 (Motor Repair Shop) HAER No. MI-116-G Page 2

service bays were filled by concrete block and the current fenestration patterns was realized. The eastern half of the structure was partitioned off by frame walls to serve as a sheet metal shop, while a storage room and office occupied the center of the building and the two western bays became a welding shop from designs by the U.S. Engineers Field Office and the Office of the Post Engineer. Today the building serves as Mobility Storage, equipment required by units during field exercises.

Sources:

Anonymous, <u>Brief History of Selfridge Air Force Base</u>, 1917-1960, unpublished ms., Air Force Historical Research Agency, Maxwell Air Force Base, Alabama, 1960.

Nigro, Louis, Selfridge Air National Guard Base, An Unofficial History, unpublished ms., Public Information Office, Selfridge ANG Base, Michigan, 1977.

Copy of construction drawing, dated May 7, 1943, U.S. Engineers Field Office, Selfridge Field, in possession of Selfridge Base Museum, Mt. Clemens, Michigan. Chagnes and Additions to Motor Repair Shop, Job N-354, Drawing No. 1/300.

Interview, Colonel Robert Stone (Ret.), Curator, Selfridge Base Museum, October 13, 1995.

Interview, Eric Reeve, Selfridge Environmental Management, October 12, 1995.

Historian:

William E. Rutter

Midwest Environmental Consultants, Inc.

May, 1996